To:

In our continuing efforts to ensure the best in customer satisfaction, Toyota is launching a Special Service Campaign (SSC) on certain 2012 model year Tacoma vehicles.

Condition:

There is a possibility that moisture in the air may cause a filter in the vehicle emissions system to degrade. This degradation could cause damage to other parts of the vehicle emission system and illuminate the check engine light (Malfunction Indicator Light).

Remedy:

Any authorized Toyota dealer will inspect the vehicle. Based on this inspection the dealer will repair the air injection pump and install an improved filter, or replace the air injection pump with one that contains an improved filter, as needed, FREE OF CHARGE. The dealer will also replace the air switching valves in the vehicle emissions system FREE OF CHARGE.

Covered Vehicles:

Model Name	Model Year	Approximate Total Vehicles	Production Period
Tacoma	2012	78,900	Late August 2011 – Early August 2012

Technician Certification Requirements

- Certified Technician (any specialty)
- Expert Technician (any specialty)
- Master Technician
- Master Diagnostic Technician

Owner Letter Mailing Date

Toyota will begin to notify owners of involved vehicles in early June 2020.

Please reference the attachments for additional details.

Thank you for your support,

TOYOTA MOTOR NORTH AMERICA

Quality I Quality Compliance Department





20TC01 - Dealer Tacoma Air Packag...20.pdf Pump...20.pdf