

Latest Vehicle Concern Fixes

POWERTRAIN



Coolant Leak	18MY Onward F PACE, XE, RR Velar equipped with AJ20P4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• The low coolant warning is on in the car.• There is a leak under the front of the car. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The leak is identified from JX73 8C362 AC <p><u>Status:</u></p> <ul style="list-style-type: none">• We are interested in gathering additional data from a vehicle before the hose is replaced.• If a leak is identified from this hose or one of the connections, please raise an EPQR and additional instruction will be provided for information to gather.	

