

## Latest Vehicle Concern Fixes

### POWERTRAIN



Coolant Leak	18MY Onward F PACE, XE, RR Velar equipped with AJ20P4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>• The low coolant warning is on in the car.</li><li>• There is a leak under the front of the car.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>• The leak is identified from JX73 8C362 AC</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>• We are interested in gathering additional data from a vehicle <b>before</b> the hose is replaced.</li><li>• If a leak is identified from this hose or one of the connections, please raise an EPQR and additional instruction will be provided for information to gather.</li></ul>	 

