

55-20-01TT - Rear Lid Will Not Open / Loses Basic Settings

Release date:

07/03/2020

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN. TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles							
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To		
Atlas, <mark>Cross</mark> <mark>Sport</mark> , Tiguan LWB	2018- <mark>2020</mark>	All	All	All	All		

Revision Table							
Instance Number	Published Date	Version Number	Reason For Update				
2058406/2	07/3/20	55-20-01TT	Update to include additional model and model year applicability.				
2058406/1	01/24/20	55-20-01TT	Original publication.				

Technical Background

Rear lid may open a few inches and stop, not able to set basic settings; rear lid may lose basic settings.

Service

With ODIS under Address word 6D Rear Lid Electronics:

- 1. Search "Rear" (Fig.1) in MVB information under control module OBD function.
- 2. Select "Status of rear lid lock", move to the right column to view and expand the values monitoring "Safety catch".
- 3. Verify the value changes for actual position of the rear lid for open & closed positions.



55-20-01TT - Rear Lid Will Not Open / Loses Basic Settings

Release date:

07/03/2020

If it's found that the value for Safety catch remains unchanged (Fig.2) for rear lid operation, replacement of rear lid latch is required.

Measured values - Select measured values		006D - Deck Lid Control Unit (UDS / ISOTP / 5Q0959107Q / 0266 / H1		
006D - Deck Lid Control Unit (UDS / ISOTP / 5Q0959107Q / 0266 /	H12/EV_De	Name	Value	
Name [IDE05229] Reason for cancellation of rear lid procedure		[IDE02093]_Status of rear lid lock		
[IDE02093]_Status of rear lid lock	>>	Rear lid lock	Rear lid lock in safety ca	atch
[IDE10804]_Easing of rear lid	>	Main catch	Open	
Filter: rear		Safety catch	Closed	
Figure 1		Figure 2		

Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.