



# Technical Service Bulletin

---

## 39 Warning lamp for sports differential on, DTC U101300 stored in the differential lock control module (quattro sport)

39 20 34 2060169/1 July 14, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
SQ8, RSQ8	2020	All	Sports Differential
Q8	2019 - 2020	All	Sports Differential
A6, A7, S6, S7, and RS7	2019 -2020	All	Sports Differential
A4, A4 allroad, S4, Q7, and SQ7	2017 - 2020	All	Sports Differential
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, Sportback, RS5, RS5 Cabriolet, RS5 Sportback, A8, S8, Q5, and SQ5	2018 - 2020	All	Sports Differential

## Condition

### Customer states:

- The sports differential warning lamp is on.
- A sports differential warning message appears.

### Workshop findings:

The following DTC is stored in the differential lock control module (quattro sport), J187 (address word 0032):

- **DTC U101300** (control unit not coded).

## Technical Background

Not applicable.



# Technical Service Bulletin

---

## Production Solution

Not applicable.

## Service

If the concern matches the conditions above, replace the control module for the differential lock control module, J187 (address word 0032) according to the Elsa Repair Manual.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	3993		
<b>Damage Code:</b>	0039		
<b>Labor Operations:</b>	Replace four-wheel-drive control module	3993 55XX 3993 19XX ( <b>Q7 only</b> )	See SRT with associated operations
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
<b>Claim Comment:</b>	As per TSB #206169/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



# Technical Service Bulletin

---

## Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
Order by VIN	The differential lock control module	01

## Additional Information

All parts and service references provided in this TSB (206169) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.