



# DETROIT™

No.: 20OEM-05

July 7, 2020

**TO:** All OEMs  
**FROM:** Application Engineering  
**SUBJECT:** DiagnosticLink® 8.12

## SUMMARY

Starting on June 9, 2020, DiagnosticLink® 8.12 (Build 4527) was made available. Current subscribers of DiagnosticLink® 8.10 or 8.11 may upgrade to DiagnosticLink 8.12 at no cost. All DTNA Service shops & OEM locations are required to maintain the latest version of software on each of their stations.

DiagnosticLink version 8.09 will no longer be functional after July 23, 2020.

**All external users with DiagnosticLink 8.03 - 8.08 installed, must upgrade their version by accessing the ordering site at <http://diagnosticlink.nexiq.com>, and downloading the latest software via the My Accounts > My Orders link.**

The next full version, 8.13, is planned for December 2020.

List of Powertrain ECUs supported:

ECU Name	CBF Version	Software Version
ACM02T	2.81.354	8.7.0.105
ACM21T	21.0.380	e7.61.1.0(MY20_RC1) e7.60.2.0(MY20) e13.55.2.0(MDEG_MY20) e7.59.2.0(MY19, HDEP_EuroV) e13.54.2.0(MDEG_MY19, ECONIC) e13.52.5.0 (MDEG_MY18) e7.58.2.0 (MY18) e9.57.1.0 (MDEG_MY17) e7.57.4.0 (MY17) e7.56.6.0 (MY16) e5.57.1.0 (MY13)
ACM301T	31.00.145	S8.50.0.203(HDEP_DD15TCO_MY20) 3.53.01.00(Stage V)
CPC02T	1.10.36	R22_00_000a
CPC04T	01.02.94	R44_00_000a(MY20) R42_00_000a(MY19) R40_00_000a(MY18) R38_01_000a (MY17) R36_00_000a (MY16 and MDEG_MY17) R34_00_00a (MY13)
CPC2	1.20.19	R05_04_000a
CPC302T	01.00.570	33.13.00(MY20_ServiceRelease) 33.03.00(MY19_Service_only_release) 31.33.00(MY19) 32.03.00(ECONIC) 29.23.00(MY18) 27.13.00(MY17)
CPC501T	02.01.031	19.32.00.00A(MY20_Production) 19.30.00.25A(MY20_series) 19.11.00.00A(MY20_pre-series)
IPPC01T	0.00.964	IPPC_2019_02_20_18.07.D1.18.01.S.019.00
MCM	2.84.36	13.4.3.0
MCM02T	4.41.145	7.7.1.47
MCM21T	21.0.461	m17.1.1.203(HDEP_DD15TCO_MY20)

		m6.8.0.1(HDEP_MY20) m14.2.1.3(HDEP_MY20_FullRangeMisfire) m14.2.2.3(MDEG_MY20) m6.7.0.2(HDEP_MY19) m12.2.2.2(MDEG_MY19, ECONIC) m12.12.0.3(HDEP_EuroV) m6.6.0.1(MY18) m12.1.2.3(MDEG_MY18) m9.1.2.3 (MDEG_MY17) m6.5.0.3 (MY17) m6.4.0.5 (MY16) m4.7.0.0 (MY13) m9.1.2.3 (MDEG_MY17) m12.1.2.3(MDEG_MY18)
MR201T	02.00.085	V30
TCM01T	0.02.045	NAMT191402(MY20_Production) NAMT191901(MY20_PreSeries) NAMT130800(MY18) NAMT117700 (MY17) NAMT095500 (MY16) NAMT070700 (MY13)
VT_J1939	00.00.34	14.13.01

List of Vehicle/Chassis ECUs supported:

ECU Name	CBF Version	Software Version
ABS02T	01.00.380	20.06.00
APS301T	01.00.341	18.33.00
BHM_J1939	00.06.45	7.43(FTL), 2.46(TBB)
BESO01T	02.01.441	-
CGW_P3	5.0.30	14.5.0
CGW02T	0.0.35	16.30.0
CGW03T	0.0.30	15.43.00
CGW04T	01.00.551	19.12.04
CLCS01T	01.01.941	16.6.0
CTP01T	01.00.621	149.200.907
DCMD02T	0.01.530	18.51.000
DCMP02T	0.01.560	18.51.000
EAPU02T	01.01.850	16.47.0
EBS01T	01.01.891	16.36.00
ECP01T	02.00.030	20.21.2
FNPAD01T	01.00.160	-
HUS01T	02.00.191	-
HVAC_F01T	1.00.326	18.44.1
HVAC_P01T	00.17.08	20.12.1
HVAC_R01T	1.00.344	18.44.1
ICU4ME	0.1.63	17.13.00(FTL), 17.13.00(WST)
ICUC01T	02.02.831	19.39.02
ICC501T	01.01.661	19.45.0
ICS01T	02.00.031	-
ICU3S_M2	00.00.397	-
ICU3S_P3	00.00.398	-
MSF_P3	7.0.34	13.25.0
MS01T	01.04.121	17.20.00
MSF01T	0.01.771	15.46.1
MPC01T	00.00.371	17.16.1
MPC02T	02.00.461	18.52.95

MUX101B	0.01.383	14.35.1
MUX201B	0.01.383	-
MUX301B	0.01.383	14.35.1
PSM01T	01.02.230	14.43.0
RDF01T	0.01.461	12.8.0
RDF02T	01.02.530	18.31.000
SAMCAB_P3	4.0.147	17.41.00
SAMCHAS_P3	4.0.80	14.28.00
SAS01T	01.01.851	16.1.0
SRRL01T	01.00.530	-
SRRR01T	01.00.581	18.34.1
SSAM02T	00.00.1301	19.06.00
VRDU01T	0.02.360	14.26.60(250Kbaud), 16.14.60(500kbaud)
VRDU02T	00.00.320	19.08.50
XMC02T	01.00.141	19.11.0
XMC202T	01.00.172	19.11.0
XMC302T	01.00.172	19.11.0
XMC402T	01.00.172	19.11.0

For more details about DiagnosticLink 8.12 features and enhancements, please visit [DTNA.com](http://DTNA.com) and select the [Service Diagnostics and Tools](#) link.

**ACCESS TO DETAILED INFORMATION**

Please contact the Detroit Customer Support Center Software support at 855-253-0423 or email [csc.software@daimler.com](mailto:csc.software@daimler.com) if you have any questions.