



69-18-01TT MIB2 - Front Seat Belt Tensioner Igniter 2 -N297- and -N298- Location

Release date: 07/31/2020

### Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, GTI, Golf R, Sportwagen/ Alltrack, eGolf	2015-2020	All	All	All	All

### Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2050931/2	7/31/20	69-18-01TT	Update model year applicability.
2050931/1	3/30/18	69-18-01TT	Original publication.


### Technical Background

Component location of the -N297- (Driver Seat Belt Tensioner Igniter 2) and -N298- (Front Passenger Seat Belt Tensioner Igniter 2).


### Service

The locations for the -N297- and -N298- are at the seat belt end fittings, located at the front door sill area, either Left or Right respectively.

The -N297- and -N298- connector can be accessed by removing the B-pillar, door sill trim and pulling back on the carpet slightly.



N297/N298 Connector Location. Driver side shown, passenger side similar.





69-18-01TT MIB2 - Front Seat Belt Tensioner Igniter 2 -N297- and -N298-  
Location

Release date: 07/31/2020

---

## Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.