

CAMPAIGN LAUNCH STATUS

NEW CUSTOMER SATISFACTION SERVICE ACTION



SERVICE ACTION N467 – DYNAMIC MODE UNAVAILABLE	
AFFECTED MODELS	20 MY RANGE ROVER SV AUTOBIOGRAPHY
VOLUME AFFECTED	44 USA 2 CAN
REPAIR	Affected vehicles may display “Special modes unavailable” message and an orange warning lamp when Dynamic Mode is selected. Vehicles requires a Chassis Control Module B (CHCM B) software update
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	July 10 th 2020
Notes	