



Preliminary Information

PIC6372A Pre-Screened MSDs (Manual Service Disconnect) To Be Acquired Through WPC has ended

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|---------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Chevrolet | Bolt EV | 2017 - 2020 | All | All | All | All |

| | |
|----------------------------|--|
| Involved Region or Country | North America |
| Condition | The Bolt EV Manual Service Disconnect Lever (with fuse) has been removed from Temporary Service Part process, part is now available through normal parts ordering. |
| Cause | A quality issue has been identified with the MSD fuse. The fuse and lever is serviced as an assembly. |

Correction:

All parts at CCA have been checked and verified stock, no further inspections are needed before installing new MSD.

This MSD can now be ordered through the regular GM CCA parts process or PQC process for required dealers.

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the correct part to order.

Version History

| | |
|----------|--|
| Version | 1 |
| Modified | 10/29/19 - Created on. 06/26/2020 - WPC ordering process has been removed for MSD |

