

GPOP - Issue Review System

Part Number: 68449322A\$, 68449323A\$, 68449327A\$

Part Description: RECEIVER, Hub (RF Hub)

Issue Description: For reports of vehicle unable to key on or instances of RFHM shows as unresponsive in WiTech topology diagnostically, please contact *FCA Redacted Content* prior to replacing this part.

If no response in 15 minutes, proceed with repair.

~_____
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
