



TEAM TIP

Release Date: December 05, 2019

SLI

Communication #: T-19-11-01

Model Year(s): 2015-2019

— Confidential and Proprietary —

VERSION: R01 (December 05, 2019)

IMPORTANT

If you are working with a printed copy, please verify you have the most current version of this document.

SUBJECT: CLUTCH MASTER CYLINDER KIT

PURPOSE

Due to a vendor change, the clutch master cylinder (PN 24249817) used on some 2015-2019 Slingshot S / SL / LE / SLR / GT models built on or before 01/18/2020 is no longer available and has been replaced with Kit 2208233.

The affected models require trimming of the footwell in order for the new clutch master cylinder boot to fit. A cut-out template is included with Kit 2208233.

AFFECTED MODELS

MODEL YEAR	MODELS	KIT
2015-2019	Slingshot S / SL / LE / SLR / GT (Built on or Before 01/18/2020)	2208233

INSTALLATION PROCEDURE

Refer to online kit instruction [9930561](#) for the installation procedure for Kit 2208233.