

Volvo Chassis - Model VNX - One piece Propeller Shaft (Drive Shaft) Contacts Cross Member




> Internal Content

Related links and attachments

The yoke of the one piece propeller shaft (Drive Shaft) MAY contact the back to back "C" channel cross member under acceleration and/or suspension articulation. The solution would be to flip-flop the propeller shaft end for end. This will give the necessary clearance.

No links or attachments available

Please refer to the images below:



Tags

K82503549

VNX

CU15

MANUAL

EATON FULLER



Feedback

[Give feedback](#) to help improve the content of this article