

CAMPAIGN FOR: King Pin Inspection

DESCRIPTION:

Need to verify king pin nut torque.

CORRECTIVE ACTION:

- 1. Pull king pin caps
- 2. Visually inspect (nuts in place, greased, worn, etc...)
- 3. If nuts are missing, replace. (Follow IMPACT procedure)
- 4. King Pin nut torque check, using torque wrench, tighten the nut until you see movement (note the torque)
- 5. Re-torque the nuts to specification (763-934 Nm 563-689 lb-ft).
- 6. Report results of inspection to James Olsen James.olsen@volvo.com

Note:

If any questions contact james.olsen@volvo.com

UCHP SCC CODE: S7520

EXPIRATION DATE: 12/31/2021

UCHP LABOR CODE: 6000-06-09-01 Steering, Inspection .3hr

CAUSAL PART: 1075914

PARTS MARKUP: na

PARTS: na