



# Preliminary Information

## PIP5707A ATS-V Engine Restriction Information

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	ATS-V	2016 - 2019	All	All	3.6 LF4	All

Involved Region or Country	North America
Condition	Brand Quality has decided to place the LF4 3.6L Twin Turbocharged engine on a restriction with the General Motors Technical Assistance Center
Cause	Inventory Control and unneeded engine replacements

### Correction:

Brand Quality has instituted a TAC based engine restriction on the LF4 twin Turbo engine. If you believe you have one of these engines that needs to be replaced, please call TAC and start a case at which time TAC will determine if we need to replace the engine or if further inspections are needed.

**NOTE: On 2016 ATS-V vehicles please follow the latest version of PIP5680 prior to calling TAC.**

If TAC determines an engine is needed, we will order it through the special parts request system.

### Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4067490	Engine Replacement	Use Published Labor Time

### Version History

Version	2
Modified	1/30/2020 - Created 08/10/2020 Updated to edit admin details.



GENERAL MOTORS