

TECHNICAL TOPICS POWERTRAIN



PCM PHEV Hybrid Battery Coolant Pump Setting P0C48

19/20 MY Range Rover, RR Sport PHEV

Customer Voice:

- The Check Engine Lamp is illuminated.

Technical Description:

- P0C48 - "Hybrid/ EV Battery Pack Coolant Pump "A" Control Circuit/ Open "is stored in the BECM.

Status:

- Follow TOPIx & PATHFINDER guidance for all DTCs stored.
- Ensure there is no air in the system.
- SSM 75005 is available to aid in diagnosis with JLRTB02056NAS1 pending sign off.
- Should no other root cause be determined, software is available in PATHFINDER version 295.
- Update the BECM with the latest software and retest.

