

Document Information

Location: Body Exterior - Closures Ancillaries

Topic: Latch replacement required

Condition: N/A

Diagnostic Trouble Codes:

N/A

Measure

McLaren have created a table to aid retailers in fitting the correct latches to different models.

There are currently 2 different door latch suppliers used by McLaren:

- Chevalier (CTL)
- Archetype

The below table explains which model was fitted with the relevant door latch in production:

Model	P11	P12	P13	P14C	P14S	P15
Door Latch Supplier						
CTL	Y	Y	Y	MY 18 and 19 Only		
Archetype				From MY20 onwards	Job 1	Job1

P11 and P12 will continue to have CTL door latches fitted in service

P13 all models will continue to be built with CTL door latches and fitted in service

P14C MY18 and 19 vehicles can be fitted with Archetype door latch but they must then be replaced as a pair as you cannot have a mix of CTL and Archetype.

Parts Information

N/A

Warranty Information

Resolution Category

Casual Part Number: N/A

Casual Part Name: N/A

Casual Issue: N/A

Rectification: N/A

Time: N/A

Attachments

N/A

KA Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.