

TECHNICAL TOPICS POWERTRAIN



P0D94 & P0D9E Stored in BCCM

19/20MY Range Rover & RR Sport PHEV

Customer Voice:

- The Check Engine Lamp is illuminated.

Technical Description:

- P0D94-00 and/or P0D9E-00 stored in the BCCM for battery charger coupler faults.

Status:

- Follow the PATHFINDER guided flows for all DTCs stored.
- Follow SSM 74964.
- BCCM software is expected to be available on PATHFINDER at the end of September with a manual patch to be made available prior the PATHFINDER availability. An SSM is expected to accompany the manual patch release.

