


TECHNICAL TOPICS

POWERTRAIN



| DTCs Stored for Coolant Pump | 19MY – Onward Range Rover, RR Sport equipped with AJ20P6 |
|--|--|
| <p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> Codes may be noted stored in the PCM in conjunction with other DTCs or during diagnosis of unrelated complaints. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> DTC P26CB-72 and/or P2B61-73 is stored in the PCM. <p><u>Status:</u></p> <ul style="list-style-type: none"> This topic is currently under investigation. Complete diagnosis of the DTCs as outlined in the TOPIx Workshop Manual (WSM) including verification of electrical circuit, pin fit, etc. If diagnosis identifies the coolant pump is faulty and requires replacement, create an EPQR which includes contact information to support PRR. |  |

