

TECHNICAL TOPICS

BODY/CHASSIS



Noise From Dynamic Suspension

17 - 20MY Range Rover

Customer Voice:

- A customer may report a hum / groan type noise in the cabin when coming from under the vehicle or a knocking noise from front suspension driving over bumps.


Technical Description:

- Noises emanating from the Dynamic Response system actuator bar (front or rear).

Status:

- Engineering are investigating noise concerns relating to the Dynamic Response system actuator bar assemblies.
- To support this investigation please submit an EPQR for any vehicle exhibiting a concern. Please include sound files or video of any noise concern, pictures of any fluid leak concern and detailed descriptions of the customers concern and when it occurs.

Dynamic Response Front Actuator



Dynamic Response Rear Actuator

