



Preliminary Information

PIP5754 Malfunction Indicator Lamp (MIL) Illuminated with DTC P262B

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT6	2019 - 2020	All	All	4.2L LTA	All

Involved Region or Country	North America
Condition	Some customers may comment that the SES lamp is illuminated or was illuminated and turned off. During inspection Technician may find DTC P262B (Control Module Power Off Timer Performance) active or stored in history.
Cause	This condition may be caused by the engine cooling down quicker than what the ECM expects after the vehicle is shut off and then restarted. This can occur in a windy area or if pulled into an air-conditioned garage for example.

Correction:

If a vehicle comes in with this DTC set, do not replace the ECM for this condition. Engineering is aware of the condition and is working on a revised diagnostic calibration to address. Clear the code and release the vehicle back to the customer.

Warranty Information

Labor Operation	Description	Labor Time
*4087608	Check ECM for DTC P262B and Clear Codes	0.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	09/28/2020 - Created on



GENERAL MOTORS