

REPLACEMENT TFT INSTRUMENT PACK SETUP GUIDANCE



Notice Information

Ref	15753
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) - September 3, 2020

TOL Ref. # 15753-SVC

REPLACEMENT TFT INSTRUMENT PACK SETUP GUIDANCE

It has come to our attention that on new spare TFT instrument packs, an issue can arise if the odometer reading is set before the instrument calibration download is carried out. If the ODO is set before carrying out the calibration download then the VIN data will not be transferred to the instruments.

Please ensure that, when fitting a new instrument assembly, you carry out the instrument calibration download before the ODO is set on any replacement TFT's to avoid this condition.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

