

TECHNICAL TOPICS POWERTRAIN



P249D-00 Stored in PCM

17MY F-PACE equipped with AJ20D4

Technical Description:

- P249D-00 DEF Dosing Adaptation Factor (trim) too high flags at key on after attempting to reset the DEF Dosing Adaptation Factor. Vehicle states it passes the routine, but the code recurs at key-on.

Status:

- Under Investigation
- If after resetting the DEF Dosing Adaption P249D-00 continues to flag at key-on, please run the adaption application with SDD monitor running and attach the CANLink files to a TA, including all initial session files.
- LTS will advise on next steps.
- Once vehicle is repaired, please raise an EPQR.

