



SERVICE BULLETIN

Classification: EL20-037	Reference: NTB20-073	Date: October 14, 2020
-----------------------------	-------------------------	---------------------------

2021 ROGUE AND 2020 SENTRA; INTELLIGENT KEY UNIT SERVICE INFORMATION

APPLIED VEHICLES: 2021 Rogue (T33)
2020 Sentra (B18)

SERVICE INFORMATION

- When replacing the intelligent key unit (hands free module), **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before NATS initialization (key registration). Once NATS initialization has been performed, portions of the configuration are locked and can no longer be changed.
- When replacing the intelligent key unit, it is critical to follow the work procedure as detailed in the ESM.
 - For Rogue, go to **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT.**
 - For Sentra, go to **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > INTELLIGENT KEY UNIT > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT.**

NOTICE

To prevent damage to the intelligent key unit, perform module configuration **BEFORE** NATS initialization.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 14, 2020	NTB20-073	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.