

# NEW SERVICE TOOLS SHIPPING TO YOUR DEALERSHIP



## Notice Information

Ref	16178
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

**TOL NOTICE (US&CA) – October 16, 2020**

**TOL Ref. # 16178-SVC**

## NEW SERVICE TOOLS SHIPPING TO YOUR DEALERSHIP

With the arrival of the Rocket 3, two new service tools will be required for your dealership to effectively service this new motorcycle family. Please be on the look-out for these two tools which have been auto-shipped to your dealership.

Part Number	Description	Models Affected
T3880501	Crankshaft Locking Pin	New Rocket 3 R/GT/TFC
T3880518	Cylinder Spacer	New Rocket 3 R/GT/TFC

We will also be shipping each dealer one roll of Fabric Tape, T2502518 in order to complete [service bulletin 584](#).

These orders can be seen in your TOL submitted orders list.

Any dealer that has already ordered the above products will not be shipped again.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.