## ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

NUMBER:

DATE:

SUBARU

18-188-16

08/24/16

## SERVICE BULLETIN

APPLICABILITY: 2015-2017MY Legacy/Outback

2016-2017MY Forester

2016MY Impreza

2017MY WRX and WRX STI

SUBJECT: **Service Manual Corrections** 

## INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2017	Legacy & Outback	Transmission	CVT(diag)-122	Diagnostic Steps changed for DTC P0776
			CVT(diag)-200-204, 206-210	Diagnostic steps changed for DTC's P2757&P2758
		Body	RAB(diag)-23	Work Support items changed
2016	Legacy & Outback	Transmission	CVT(TR580)-8,28,32,245-247, 250-252	Specalty Tool added and steps for its use added
			CVT(diag)-124	Diagnostic Steps changed for DTC P0776
		Body	AB(diag)-40,91	Diagnostic Steps changed for DTC B1652
2015	Legacy & Outback	Body	SRVD(diag)-41	Diagnostic Steps added for DTC B2328

Bulletin Number: 18-188-16; Date: 08/24/16

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2017	Forester	Diagnostics	Diag Procedure with DTC	Diagnostic Steps changed for DTC P0776
				Diagnostic steps changed for DTC's P2757&P2758
			Work Support	Work Support items changed
		Body & Electrical Wiring System	Engine Electrical	New diagrams
			Front Wiper \$ Washer	New diagrams
			Power Window	New diagrams
			Radiator Fan	New diagrams
			Rear Wiper & Washer	New diagrams
2016	Forester	Transmission	General Description	Specalty Tool added and steps for its use added
			Diag Procedure with DTC	Diagnostic Steps changed for DTC P0776
2016	Impreza	Engine 1	CO(H4DO(w/oHEV))-10	New wiring diagram
		Transmission	CVT(TR580)-8,27,31,218-220, 223-225	Specalty Tool added and steps for its use added
			CVT(w/o HEV)(diag)- 143-145,147-149	Diagnostic steps changed for DTC's P2757&P2758
			CVT(HEV)(diag)-189-194	Diagnostic steps changed for DTC's P2757&P2758
		Wiring System	WI (w/o HEV)-116,190	New wiring diagram
			WI (HEV)-82,96,169	New wiring diagram
2017	WRX & WRX STI	Transmission	CVT(diag)-87	Diagnostic Steps changed for DTC P0776
			CVT(diag)-146-148, 150-152	Diagnostic steps changed for DTC's P2757&P2758
		Body	RAB(diag)-22	Work Support items changed