

Fel-Pro Notification: FS7734PT-2, HS7734PT, MS9344SH, 260-1571

A manufacturing error has been identified with the intake manifold gaskets packaged in the sets listed above. The intake manifold gaskets are missing the embossment. The embossment is the main sealing element on the surface of the intake gaskets and gets compressed during installation. When compressed, the embossment increases contact stress/load, which is designed to seal the intake air/fuel mixture, coolant and exhaust between the intake manifold and cylinder head. Without this embossment on an intake manifold gasket, the gasket will not be able to properly seal the application. The following issues may occur if these gaskets are installed: internal and/or external coolant leaks, vacuum leaks, and exhaust leakage. If these conditions are allowed to persist, they may result in poor engine performance and drivability, engine overheating, and internal engine damage.

All manufacturing and distribution inventory has been placed on hold and no additional sets will be released until the part is corrected.

Credit will be issued to your account upon receipt of affidavit form.

- 1. Please visually inspect parts within the packaged label date codes shown below and scrap the parts using the affidavit form included.
- Email a copy of the completed affidavit to warranty@driv.com *Subject line: RGA25191*
 - a. If you have any questions, please call 734-384-7898 and speak with a Warranty CSR
- 3. Reorder replacement product, as required.

Pictures of the locations of the date codes on the affected sets can be found below.

Issue detail

Below is an image of the nonconforming gasket.





Date codes affected

Set Number	Date	Date Code on Box
SFS7734PT2	30-Sep-20	200929
	10-Sep-20	200909
	19-Aug-20	200818
SHS7734PT	12-Oct-20	201011
	31-Aug-20	200830
	19-Aug-20	200818
SMS9344SH	01-Oct-20	200931
	23-Sep-20	200922
	18-Sep-20	200917
	17-Jul-20	200716
	12-Jun-20	200611
S2601571	20-Sep-20	200919
	29-Jul-20	200728

Date code location examples







7450 McCormick Blvd Skokie, Illinois 60076 DRiV.com













AFFIDAVIT OF DESTRUCTION

DAF#:		
Customer Ref #:		
Customer:		
Customer Acct #:		
DC Location and #:		
We, the undersigned, certify that we	e personally witnessed and or supervise	ed the destruction of the attached list(s) of
BRAND NAME		
We further agree that DRiV will not b	be responsible for any future requests	for credit on these specific sku's at this location.
Product has been: ☐ Destroyed in field – under 60 un ☐ Shipped To:	its	
(for destruction)		
 Provide a photo of product, 	ile with the final inventory list of the p unpackaged & spray painted, (IF LESS) rom a scrap yard for inventories above	
Destruction took place on/	/ 2020	
At		
Signatures required: must be signed	by DRiV personnel and customer	
DRiV Signature	Customer Signature	
DRiV Printed Name/Title	Customer Printed Name/Title	