

## Document Information

**Location:** Electrical - Tyre Pressure Monitoring System

**Topic:** Rear tyres temperature delta

**Condition:** Intermittent

**Diagnostic Trouble Codes:** N/A

## Measure

A rear tyre temperature delta of up to 7 degrees centigrade higher (between LH & RH rear) may be experienced during normal vehicle running.

This is normal. As long as the tyre temp. delta (between LH & RH rear) returns back to being equal or is at ambient temperature after an overnight sleep cycle (prior to any driving), then there is no issue with the TPMS or IC system.

This delta can be seen during normal driving cycles due to different heat zones within the rear tyre envelopes.

## Parts Information

N/A

## Warranty Information

Resolution Category

Casual Part Number: N/A

Casual Part Name: N/A

Casual Issue: N/A

Rectification: N/A

Time: N/A

## Attachments

N/A

## KA Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.