

GPOP - Issue Review System

Part Number: 68384455A\$, 68416785A\$, 68384452A\$, 68416782A\$, 68384454A\$, 68416784A\$

Part Description: TRANSMITTER, Integrated Key FOB

Issue Description: For concern of keyfob inoperative, please contact FCA Redacted Content prior to replacing/servicing keyfob.

If no response within 15 minutes, proceed with repair.

Engineering is investigating to determine root cause as warranty return keyfobs are determined trouble not found.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

