

TECHNICAL TOPICS

POWERTRAIN



Unable to Fuel Vehicle	20/21 MY Range Rover, RR Sport PHEV
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- Fuel spits back every time the vehicle is fueled, Fuel pump keeps shutting off and cannot fill vehicle <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- P2418- 03 “EVAP System Switching Valve Control Circuit/ Open” is stored in the PCM <p><u>Status:</u></p> <ul style="list-style-type: none">- Perform all checks outlined in the WSM related to P2418-03- Should a replacement of the Fuel Tank Vent Valve be necessary and resolve the customer concern, please raise an EPQR with a clear description of the issue and fix as well as your parts manager mailing information	

