

## TECHNICAL TOPICS

### BODY/CHASSIS



#### Front Power Seat Switch Malfunction

#### 20MY Range Rover

##### Customer Voice:

- A customer may report that the front seat is not operating properly from the switch pack, features like seat massage, lumbar support, seat memory, etc. is not working from the switch.

##### Technical Description:

- The front seat switch pack is being replaced for different operational concerns.

##### Status:

- Engineering is investigating reports of reports of front seat switch pack failures.
- To support this investigation, should a customer report a concern regarding seat switch operation and the cause is determined to be due to a faulty seat switch pack, please submit an EPQR with details of the seat operational concern.

