



DEALER HOLD

Release Date: December 23, 2020

SLI

Communication #: TDH-20-04

Model Year(s): 2021

— Confidential and Proprietary —

VERSION: R02 (December 29, 2020)

****Added reflector decal installation process****

IMPORTANT STOP SALE NOTICE!
Stop selling affected vehicles immediately.

SUBJECT: DEALER HOLD - BODY REFLECTORS

PURPOSE

Polaris has found that some Slingshot models may have been manufactured without the driver's and/or passenger's front side reflector(s).

To resolve this issue, the driver's and passenger's side reflector decals must be present prior to sale and registration.

AFFECTED MODELS

MODEL YEAR	MODELS	VEHICLE IDENTIFICATION NUMBER RANGE
2021	Slingshot R / S / SL	Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to lookup affected VINs.

WARRANTY CLAIM PARTS INFORMATION

SLINGSHOT R / S / SL – PASSES INSPECTION	
Bulletin	TDH-20-04A
Claim Type	Dealer Hold
Labor Allowance	0.2 hours (12 minutes)
Part Number / Description	0000541 (QTY 1) Bulletin Misc Labor
Parts Availability	NA

SLINGSHOT R / S / SL – FAILS INSPECTION/REQUIRES REFLECTORS	
Bulletin	TDH-20-04B
Claim Type	Dealer Hold
Labor Allowance	0.4 hours (24 minutes)
Part Number / Description	5451345 (QTY 1) Reflector, LH 5451346 (QTY 1) Reflector, RH
Parts Availability	Available to order

The information contained within this document is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Inc. This document is provided for the sole use of authorized Polaris dealers and distributors. This document is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Inc.

TDH-20-04 PROCEDURE

REFLECTOR INSPECTION PROCEDURE

1. Inspect that the driver's side reflector decal is present and secure.



2. Inspect that the passenger's side reflector decal is present and secure.



3. If both reflector decals are present, the vehicle may be sold. File a Dealer Hold claim for TDH-20-04A.
4. If either reflector is missing, the vehicle cannot be sold until both reflectors are present. Proceed to REFLECTOR INSTALLATION.

IMPORTANT

If the vehicle is missing any decals, do NOT file TDA-20-04A.

REFLECTOR INSTALLATION (IF MISSING)

1. Clean the locations where the LH and RH Reflectors are to be installed using a clean rag and isopropyl alcohol.
2. Install the LH and RH Reflectors. See steps 1 and 2 of the REFLECTOR INSPECTION PROCEDURE for proper locations.
3. File Dealer Hold TDH-20-04B.

The information contained within this document is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Inc. This document is provided for the sole use of authorized Polaris dealers and distributors. This document is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Inc.