



SERVICE BULLETIN

Classification: EC20-030	Reference: NTB20-093	Date: December 16, 2020
-----------------------------	-------------------------	----------------------------

2021 ROGUE; INTELLIGENT KEY UNIT DTC B203D-14 DIAGNOSTIC PROCEDURE

APPLIED VEHICLES: 2021 Rogue (T33)

SERVICE INFORMATION

DTC B203D-14 indicates a concern in the circuit between the inside key antenna and the intelligent key control unit. Currently, the ESM does not have a diagnosis or repair procedure for DTC B203D-14.

When DTC B203D-14 is confirmed, perform the diagnosis and repair procedures, outlined in the ESM, for DTC B203C-14.

- For DTC B203C-14 diagnosis and repair procedure, refer to the ESM section: **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > DTC/CIRCUIT DIAGNOSIS > B203C-14 INSIDE ANTENNA.**

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 16, 2020	NTB20-093	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.