

[Translate](#)

ROADSTER Trailer Module Failure (RT-622) - 109338

[Printable Version](#)[Rate This Article](#)

(Average Rating: No Rating)

Version 1

Language

English ▼

[Show Properties](#)**Summary:**

Trailer module may failed. Add ground harness to prevent further failures.

Type:

Solution

TST Detail:**PROBLEM**

The trailer module may fail.

SOLUTION

Refer to [Warranty Bulletin 2013-4](#) to install the trailer harness ground kit p/n 219400537

Attachment:

First Published By: Francois Yergeau on 2015-02-09

Last Modified By: Dany Davey on 2015-11-03