

FT4971 A/C ON tell tale not working properly

Technical writer name
Devanand

Manual section 14

| Description | Program | Rev |
|--------------|----------------|-----|
| VBEA Program | FB_HOU4DE_M_01 | C |
| VBEA Program | FB_HOU4DE_M_02 | A |

Nb hours Level 1 0.33 hr

MQR 7621-2166

| Disposal of parts | | |
|--------------------|----------|---|
| Removed parts are: | | When the retained check box is check, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed, |
| Discarded | Retained | |
| - | - | |

| Client | Order | Road numbers | | VIN | | QTY | Lang. | Customer | Target market | Plant | Config moteur | Model | Program | Rev | NR | R1 |
|-----------------------|-------|--------------|------|---------------|---------------|-----|-------|----------|---------------|-------|---------------|-------|----------------|-----|----|----|
| Houston Texas - Metro | LC91 | 2500 | 2501 | L82J4L9777479 | L82J0L9777480 | 2 | E | US-Prv | US | PLB | TD | 40 | FB_HOU4DE_M_01 | C | x | |
| Houston Texas - Metro | LC92 | 2502 | 2534 | L82J8L9777601 | L82J3L9777618 | 33 | E | US-Prv | US | PLB | TD | 40 | FB_HOU4DE_M_02 | A | x | |