

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2021010002 January, 2021

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 907 Model Year 2019**
Replace Folding Parking Brake Lever Label

MBAG, the manufacturer of Mercedes-Benz Sprinter Vans, has determined that the folding parking brake lever label is not in the correct language (English).

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately **14** vehicles are affected.

Order No. V-SC-2021010002

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

Model 907
with code BE2 (Handbrake lever, folding)
with code ZU8 (National version for USA)



Operation no. of the operation texts or standard texts and flat rates



Category	Op. no.	Operation text	Time	Acc. no.	Code
L	02 1193	Operations: Replace information label for folding parking brake lever	0.2 hrs	42 930 93	VS3FOLEVER

23 Information label



D00.10-A074-03

	Check		
1	Check, whether the vehicle is affected by the measure.	 For authorized Mercedes-Benz service partners, only the entry in the Extended VEGA Application (EVA) system, in the "Current" tab, is decisive. An additional test of the affected vehicles in the workshop information system (WIS) or vehicle list is thereby not necessary.	

	Replace		
2	Replace information label (23) for folding parking brake lever.	 Bonding surface must be absolutely free of dust and grease. Otherwise, a sufficient degree of adhesion cannot be assured.  The information label (23) is located next to the start/stop button. Cleaner	BR00.45-Z-1025-04A

Repair materials

Number	Designation	Order number
BR00.45-Z-1025-04A	Cleaner	A 005 989 19 71

Parts ordering note

Part no.	Designation	Quantity
A 906 584 85 07	Information label	n. B.