



# SERVICE BULLETIN

Classification: AT14-016F	Reference: NTB15-013F	Date: February 19, 2021
------------------------------	--------------------------	----------------------------

## NISSAN; PROCEDURE TO CLEAN CVT TRANSMISSION FLUID COOLERS

**APPLIED VEHICLES:** 2013-2015 Altima (L33) – 4 cylinder and V6  
 2016-2018 Altima (L33) – V6 only  
 2015-2017 Juke (F15)  
 2016-2020 Maxima (A36)  
 2015-2020 Murano (Z52) – V6 only  
 2013-2020 Pathfinder (R52) – V6 only  
 2015-2017 Quest (E52)  
 2014-2020 Rogue (T32)

**APPLIED TRANSMISSION: CVT**

**This bulletin is no longer active.**

Please discard previous versions of NTB15-013.  
 Refer to the ESM for the fluid cooler cleaning procedure.

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 12, 2015	NTB15-013	Original bulletin published.
September 9, 2015	NTB15-013a	APPLIED VEHICLES and SERVICE PROCEDURE sections revised
April 7, 2016	NTB15-013b	APPLIED VEHICLES section revised
June 9, 2016	NTB15-013c	APPLIED VEHICLES section revised
April 24, 2017	NTB15-013d	APPLIED VEHICLES section revised
October 31, 2019	NTB15-013e	APPLIED VEHICLES and PARTS INFORMATION sections revised
February 19, 2021	NTB15-013f	Bulletin no longer active

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.