



UPDATE: 18MY JAGUAR F-PACE / LAND ROVER  
RANGE ROVER VELAR - UNABLE TO COMPLETE PDI  
AND ACTIVATE TELEMATICS SYSTEM: INTERIM PDI  
ADVICE

SERVICE ALERT

29-NOV-17

NO.: JA17TE-06  
SA17TE-07  
(ISSUE 2)

SEC.: TOOLS &  
EQUIPMENT

MKT.: CAN / USA

This Service ALERT is superseded by the following SSM's which include an expanded vehicle range and service instructions.

Please refer to the following publications on TOPIx for the latest details.

Jaguar SSM #73634

Land Rover SSM #73635

For questions regarding the content of this publication, please contact:  
Thomas Bollettieri      Product Investigation Specialist - Electrical Systems  
201-818-8339      [tbollett@jaguarlandrover.com](mailto:tbollett@jaguarlandrover.com)

Jaguar Land Rover North America, LLC  
555 MacArthur Boulevard  
Mahwah, NJ 07430