

FT5063 Hydraulic pipes brazing failure LC27 LC92

Technical writer name / nom rédacteur technique: Annie St-Jacques

Manual/manuel, section: 9

Parts/ pièces, description	Part # / # de pièce	QTY / Qté
PIPE SUPPLY ASSY STEEL	N77549-01	1

Labour level 1 / main d'oeuvre niveau 1	4h
---	----

MQR	7621-2169
-----	-----------

Disposal of parts / disposition des pièces	
Removed parts are / les pièces retirées sont:	<p><b>Return removed pipe with the following informations:</b></p> <ul style="list-style-type: none"> <li>- Reference: REQUEST ID 7442;</li> <li>- Pipe manufacturer label and part number;</li> <li>- Bus order, Bus road number.</li> </ul> <p>To:</p> <p>Protopshop Nova Bus (attn: Orphée Corriveau)                      212 Rue Poirier                      St-Eustache, Canada                      J7R 5R3</p>
Discarded / jetées	
Retained/conservées	
	X

Client	Order/Lot	Road numbers / No de véhicule		VIN / NIV		QT Y / QT É	Lang.	Customer Group/ Groupe client	Target market / marché cible	Plant / Usine	Engine Config / Config moteur	Model / modèle	NR	R1
Houston Texas - Metro	LC92	2506	2506	L82J8L9777589	L82J3L9777589	1	E	US-Prv	US	PLB	TD	40	x	
Houston Texas - Metro	LC92	2516	2516	L82J8L9777592	L82J3L9777592	1	E	US-Prv	US	PLB	TD	40	x	
Houston Texas - Metro	LC92	2531	2531	L82J8L9777594	L82J3L9777596	1	E	US-Prv	US	PLB	TD	40	x	
Maryland Transit Authority - MTA	LC27	20005	20005	L82J6L9777631	L82J6L9777631	1	E	Us-Prv	US	PLB	TD	40	x	
Maryland Transit Authority - MTA	LC27	20015	20015	L82J2L9777643	L82J2L9777643	1	E	Us-Prv	US	PLB	TD	40	x	
Maryland Transit Authority - MTA	LC27	20029	20029	L82J2L9777657	L82J2L9777657	1	E	Us-Prv	US	PLB	TD	40	x	