

FT5044 CATA Operator's Complain of Seat Alarm Sensitivity

Technical writer name
Devanand

Manual section 12

| Material | Part Number | QTY |
|----------|-------------|-----|
| - | - | - |

Nb hours Level 1 0.33 hr

MQR 7621-2263

| Disposal of parts | |
|--------------------------|---|
| Removed parts are: | When the retained check box is check, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed. |
| Discarded | Retained |
| - | - |

| Client | Order | Road numbers | | VIN | | QTY | Lang. | Customer | Target market | Plant | Config moteur | Model | NR | R1 |
|---|-------|--------------|------|---------------|---------------|-----|-------|----------|---------------|-------|---------------|-------|----|----|
| Capital Area Transportation Authority Michigan - CATA | LD34 | 719 | 730 | L82J8L9777730 | L82J2L9777741 | 12 | E | US-Prv | US | PLB | TD | 40 | x | |
| Capital Area Transportation Authority Michigan - CATA | LD35 | 6016 | 6018 | S92J3L9777742 | S92J7L9777744 | 3 | E | - | US | PLB | | 60 | x | |