

CAMPAIGN LAUNCH STATUS

N560 SERVICE ACTION 19-21MY RANGE ROVER, RR SPORT



OWNER NOTIFIED SERVICE ACTION - N560 POWERTRAIN CONTROL MODULE (PCM) UPDATE

AFFECTED MODELS

19-21MY Range Rover Sport; 20-21MY Range Rover models fitted with the P6 3.0L Engine

VOLUME AFFECTED

42,704 USA 2,811 CAN

REPAIR

Affected vehicles will receive a Powertrain Control Module (PCM) software update which includes a revised engine protection strategy. This is to prevent engine stumbles, misfires and rough running at idle with a potential MIL illumination.

REPAIR TIME

Est 0.2hrs+Drive in/out

CAMPAIGN LAUNCH

March 3rd 2021

Notes

Owner mailing will commence March 18th, 2021.



PRINTED COPIES ARE UNCONTROLLED