

TECHNICAL TOPICS

BODY/CHASSIS



Poor Air Flow From Rear Face Vents (4 Zone Climate Control Only)

21MY F-PACE

Customer Voice:

- A customer may report poor air flow from the rear face vents located in the back of the center console.

Technical Description:

- For models with 4 zone climate control only, the air vent ducting in the center console may have been incorrectly positioned during manufacturing.

Status:

- **SSM 75300** has been published to provide repair guidance to correct this concern.
- Service Action H343 is going through sign-off to proactively address this concern on affected vehicles.

