

GPOP - Issue Review System

Part Number: R8003108A\$, R8003109A\$, R5179337A\$, R8039494A\$, R8018639A\$,
R8434004A\$, R8003114A\$, R8434027A\$, R8003115A\$, R8147484A\$,
R5104552A\$, R5166351A\$, R8148948A\$, R8148949A\$, R5144486A\$,
R8156209A\$, R8149256A\$, R2120027A\$

Part Description: NAG1 Transmission

Issue Description: Before installing the transmission with the engine, check for dowel pins (2) for alignment. If the pins are missing request to add the dowel pin first and then install the transmission

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.