

DTNA Solutions > Discussions and Feedback > Tech Talk

> New Beam clamp for harness routing 23-14234-002



Robert\_Cadell\_J

MacGyver

04-28-2021 09:30 AM

New Beam clamp for harness routing 23-14234-002 

### Vehicle Information

VIN: 1FVACXFE2MHMP0744

Model: M2 106 CONVENTIONAL CHASSIS

Model Year: 2021

Mileage: 20 miles

Make: FTL

Are you currently seeing this same issue on other DTNA vehicles at your location?: no

Base Model: M2106

### Vehicle Systems Involved

OTHER SYSTEM (Beam clamp  
(new part ))

Wanted to share this also Checking over a unit for delivery and found a beam clamp but nothing like I'd seen before, was holding the fuel level wiring there's adhesive on the top and a slide on the bottom to secure it P/N 23-14234-002



Someone had a Cool idea.

Add tags

 1 Kudo

Reply

