


TECHNICAL TOPICS

POWERTRAIN



<p>Transmission Leak</p>	<p>17-18MY Range Rover, RR Sport, Discovery</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - There is a fluid leak on the ground. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - The leak is identified as a transmission fluid leak coming from the housing as referenced in LTB01255. <p><u>Status:</u></p> <ul style="list-style-type: none"> - Cleaning the area prior to repair with the Devcon putty is a critical step. - Ensure the area is fully cleaned and free of oil residue when performing the repair to mitigate the risk for repeat complaints. 	 <p>Use a suitable solvent-based cleaning fluid to thoroughly clean the highlighted area of the transmission.</p>



PRINTED COPIES ARE UNCONTROLLED