

TECHNICAL TOPICS

BODY/CHASSIS



2nd Row Seat Tilt Feature Change

Customer Voice:


- A customer may report that the 2nd row seat back does not tilt forward for access to the 3rd row seats when the switch located at the top of the 2nd row seat is pressed.

Technical Description:

- The seat module software strategy has changed for 21MY for this feature. The rear window isolator button will now inhibit the 2nd row seat tilt switch located on the top of the seat as well as the rear windows.
- The load space switch and the front touch screen will still tilt/ fold the 2nd row seats regardless of the rear window isolation switch position.

Status:

- Should a customer express a concern, please ensure the rear window isolation switch is not activated to inhibit seat movement from the seat switch.
- SSM 75319 has been published to inform you of this change in operation.



21MY RR Discovery



PRINTED COPIES ARE UNCONTROLLED