

TECHNICAL TOPICS

BODY/CHASSIS



Deployable Side Steps Not Operating	21MY Discovery
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - A customer may report that the deployable side steps are inoperative. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - The Deployable Side Steps (DSS) module may have gone offline as the vehicle CAN bus network awakes. <p><u>Status:</u></p> <ul style="list-style-type: none"> - SSM 75305 has been published to provide repair guidance to correct this concern. - Should a customer express a concern, please refer to this SSM for repair guidance. 	

