

**Classification:**

AT13-019a

**Reference:**

ITB13-035a

**Date:**

August 18, 2014

## CVT FLUID LEVEL CHECK SERVICE INFORMATION

The APPLIED VEHICLES section has been revised. No other changes have been made.  
Please discard all previous versions of this bulletin.

**APPLIED VEHICLE:** 2013 JX35 and 2014-2015 QX60 (L50)


**APPLIED VIN and DATE:** Vehicles built AFTER 5N1AL0M(\* \*)DC 343902 and March 26, 2013

**APPLIED TRANSMISSION:** Vehicles equipped with CVT ONLY

### SERVICE INFORMATION

Applied vehicles equipped with a CVT have a "cap" that appears to be a fluid level gauge. This "cap" will NOT have a gauge or "dipstick". This is normal. Do NOT replace the "cap" because it is thought to have a "dipstick".

The fluid level is not checked from this location. The fluid level for applied vehicles is checked from the oil pan (refer to the appropriate section of the Electronic Service Manual (ESM)). Whenever checking, filling, or topping off a CVT's fluid level of an applied vehicle for any reason, use the procedure outlined in the appropriate section of the ESM.



Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.