

Classification:

ST14-011

Reference:

ITB14-046

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

September 17, 2014

## 2014 Q50; DAST CALIBRATION STEERING WHEEL OFF-CENTER AFTER CALIBRATION

**APPLIED VEHICLES:** 2014 Q50 Sedan (V37) equipped with DAST  
2014 Q50 Hybrid (V37)

### SERVICE INFORMATION

When performing Direct Adaptive Steering (DAST) Calibration (Mode 1):

- **Always use an alignment rack** with the front wheels positioned on the turntables and the pins removed. The front wheels must be allowed to move freely.
- **DO NOT** perform DAST Calibration (MODE 1) with the front wheels in any other position then listed above.

**NOTE:** As of the publication date of this bulletin, the Electronic Service Manual (ESM) states; "Lift up vehicle or set the front wheels on the turntable". Lifting up the vehicle is incorrect.

- To prevent damaging the spiral cable during DAST Calibration (MODE 1), follow instruction in the ESM.

After performing DAST Calibration (MODE 1), if there is a steering wheel off-center or a vehicle pull condition, perform DAST Calibration (MODE 1) again, making sure to use an alignment rack.

**NOTE:** Do not perform a wheel alignment for a steering wheel off-center or pull condition.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.