



SERVICE BULLETIN

Classification: BT15-005	Reference: NTB15-018	Date: March 12, 2015
-----------------------------	-------------------------	-------------------------

2015 ALTIMA “S”; LEATHER INTERIOR TRIM SERVICE INFORMATION

APPLIED VEHICLE: 2015 Altima (L33) WITH “S” LEVEL TRIM ONLY

APPLIED VINs and

DATES: Vehicles built **ON OR AFTER** 1N4(*)L3AP(*)FC 247385 and
January 12, 2015

OR

1N4(*)L3AP(*)FN 383232 and
January 12, 2015

SERVICE INFORMATION

The build specification for 2015 Altima vehicles with “S” trim has changed.

2015 Altima vehicles with “S” trim built on or after the **APPLIED VINs and DATES** stated above come **standard** with leather door finishers (door panels) and leather center console lid along with cloth seats.

DO NOT REPLACE* the leather door panels and leather center console lid with cloth door panels and cloth center console lid on 2015 Altima vehicles with “S” trim built on or after the **APPLIED VINs and DATES** stated above.

*** NOTE: Replacing door panels and leather center console lids for this condition is not a warrantable expense.**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.