

Classification:

BT15-010

Reference:

ITB15-016

Date:

April 20, 2015

COMBINATION METER FRONT COVER SERVICE PART AVAILABLE

APPLIED VEHICLES:


2013 EX (J50)
 2013 FX (S51)
 2013 G37 Convertible (V36)
 2013 G37 Coupe (V36)
 2013 M (Y51)
 2013 M Hybrid (HY51)
 2013 QX (Z62)
 2015 Q40 (V36)
 2014-2015 Q50 (V37)

2014-2015 Q50 Hybrid (V37)
 2014-2015 Q60 Convertible (V36)
 2014-2015 Q60 Coupe (V36)
 2014-2015 Q70 (Y51)
 2014-2015 Q70 Hybrid (HY51)
 2014-2015 QX50 (J50)
 2014-2015 QX70 (S51)
 2014-2015 QX80 (Z62)

SERVICE INFORMATION

If you confirm there is a need to replace the combination meter front cover (lens) on an Applied Vehicle for any reason (scratch, blemish, etc.):

- Do not replace the entire combination meter assembly. The front cover of the combination meter assembly is available as a separate service part.
- Refer to the Electronic Service Manual, section MWI–Meter, Warning Lamp & Indicator, for replacement information.



PARTS INFORMATION

Refer to FAST or your electronic parts catalog to determine the correct part number for your vehicle.

CLAIMS INFORMATION

Refer to the current Infiniti Warranty Flat Rate Manual and use the appropriate claims coding for repairs performed.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.